

Popular Assemblies




Unusual Slings Conditions

Recommended Load Factors for unusual slinging conditions, normally applied to W.L.L. of a single sling.


Temperature Loadings: Applicable to chain temperature.

- 40° C to + 200° C	+ 200° C to + 300° C	+ 300° C to + 400° C
1	0.9	0.75


Edge Loadings: *Applicable to load lifting and load lashing.*



$r = \text{more than } 2 \times \text{chain size}$
1



$r = \text{more than chain size}$
0.7



NOT RECOMMENDED
WITHOUT CORNER PROTECTION